



ORNL



NEUTRON SCIENCES



Cuvette Cell Washer
0023-4061



5

**Cleaning Solution
Reservoir**

6

Wash Platform

Washer Funnel

4

Rubber Seal


3

Flask


2

**Connection to
Vacuum Source**


1



SETUP



OPERATION



HAZARDS



SLIP HAZARD

Spilled liquids may cause slip hazard.



FUME HAZARD

Some solvents used for cleaning cells may generate harmful fumes.



SHARPS HAZARD

Some materials being cleaned with this device may create a sharp hazard if broken.



CHEMICAL EXPOSURE HAZARD

Splashing in the eyes or on the skin may occur when using this device.

PREVENTION



EYE PROTECTION

Wear safety glasses while operating.



PROTECTIVE GLOVES

Wear appropriate gloves for heat and chemical usage.



NON-SLIP, CLOSED SHOES

Wear non-slip, closed shoes to avoid spills.



READ MANUAL

Become familiar with this guide before operating.

For additional help contact the Lab
Space Manager